

Download 2007 Freightliner Columbia Repair Manual

Campaign: 07V302000 on 07/15/2007 Component: Service brakes, air:supply:check valve Manufactured: 06/30/2002 - 07/02/2007 Affected: 75,000 Defect: Certain freightliner school bus chassis, heavy trucks, and thomas built school buses manufactured between july 2002 and july 3, 2007, equipped with bendix sr-7 spring brake control valves. Page 1 © CASCADIA Driver's Manual Part Number STI 478 Publication Number STI-478-6...; Page 2 To preserve our environment, fol- This vehicle must be regularly inspected and main- low appropriate environmental rules and regulations tained as indicated in the Cascadia Maintenance when disposing of materials. Manual, and in the Pre- and Post-Trip Inspections...i have a 2004 freightliner columbia with a mercedes engine. engine serial number is xxxxx the right side of engine caught fire because of the alterantor chargeback wire rubbing into frame.05 freightliner columbia i have a-ABS code 136 sid 03 fault 05 - Answered by a verified Technician